

Dripping
water has
got behind
the cracking
texture and
caused this
area of
failure






## **BEFORE**



























Even the signage will stay bright and new in thanks to Thermo-shield Exteriors long lasting protection and fade fighting colors

