




**Stucco exterior
was cracking and
"would come off
in your hand if
you brushed it".**

**Windows and detail areas get an extra coat of Thermo-shield Exterior.
2 coats will give this 15 year old stucco new color, waterproofing, and insulation.**





**Thermo-shield
Exterior**

**Un-coated
Stucco**



Owner of this home noticed right away the sound proofing qualities of the Thermo-shield micro-spheres. A neighbor to the right owns a large, loud, diesel truck which he starts every workday at 5:00 am.


After a few days with the system on I awoke about 7:00 and jumped up, worrying that I had not heard his truck for a couple of days and thought something was wrong. When I looked his truck was gone and I never even heard it ! I got up early the next morning and could barely hear his truck. I put my ear on the wall that had Thermo-shield on it and the sound was muffled and faint. I also checked the front wall, which is not covered, and I could hear it very loud.



Old stucco surface

The image is a side-by-side comparison of two stucco surfaces. The left side shows a weathered, yellowish-tan stucco with a rough, porous texture and some visible cracking. The right side shows a similar stucco surface but with a dark, vertical shadow line on the left side, indicating a protective layer. The text 'Old stucco surface' is positioned in the upper left quadrant of the left panel, and 'Stucco protected by Thermo-shield' is positioned in the lower right quadrant of the right panel.

**Stucco protected by
Thermo-shield**



Un-coated

coated



**Same corner with
front finished**

Before



After



**Restored, Beautified, Protected, and Insulated
with Thermo-shield Exterior Ceramic Coating**

