

**Commercial
building in
Comstock, Nevada
gets new Thermo-
shield Roof**





**The Reno area dealer who applied this project measured air temps and attic temps, for before and after tracking, and for his own peace of mind.
(It was his first project)**

New Thermo-shield Roof applied to building. The week of application the air temperatures were in the low 90's and attic temps were over 150 degrees. After application the temperature in the attic was 99 degrees, just a few degrees warmer than the air temperature. Constant checking during the summer shows the attic temps never rise over 5 degrees of air temps.



Owner and tenants have all commented on how good the roof now looks and how cool the building stays. Everyone is excited to compare energy costs monthly and they tell everyone about it !





As a side note I always try to coat the entire pipe, jack, or flashing. This restores, protects, and beautifies everything on the roof and gives a wonderful, clean finish look that you do not see on this example with the black and silver pipes

