

**Leaks were a big problem on this 9 unit apartment in Salt Lake City. Owner could not afford an entire new system but needed to stop the water from coming in, Thermo-shield to the rescue. Leaks solved and owner will finish entire system as her budget allows.**



## Laps on epdm rubber roof are failing and leaking



**These laps have been repaired already using white faced epdm over field laps. These repairs only held up 3 years.**






**Thermo-shield and  
fabric on laps and  
around all pipes**



**All laps and pipes  
are water-proofed  
using Thermo-  
shield**

**Thermo-shield's remarkable adhesion allows it to bond to plastic, galvanized metal, and rubber, all found on this roof**





**All laps and trouble areas are repaired using  
Thermo-shield Roof**